

NO. 89789
FRAME NO. 41

U-89

89789

1

8000

LN5-RN1

ELVINS

SL
(STAINED)

BERM

SL

(B)

SL

SL


- LEGEND
- (A) TAILINGS MOUND
 - (B) CHAT TAILINGS
 - (C) PARTIALLY REVEGETATED TAILINGS
 - (D) TAILINGS PILE
 - (E) ERODED TAILINGS
 - (L) LANDFILL
 - DG - DISTURBED GROUND
 - SL - STANDING LIQUID
 - SW - SOLID WASTE
 - FL - FILL
 - WL - WETLANDS
 - UNB - UNBUILT
 - EX - EXCAVATION PIT
 - DR - DRAINAGE
 - FR - FLOW

(A)

Bluffs Branch

ST. JOE
STATE PARK

BIG RIVER MINE TAILINGS
ST. FRANCOIS COUNTY, MISSOURI
PIC 89789 SITE ID. NO. MO-ZZ
DATE FLOWN: APRIL 20, 1989
SOURCE: EMSL FRAME NO. 41
APPROX. SCALE 1 inch = 333 feet



30059265



Superfund

EPA Environmental Monitoring
Systems Laboratory-Las Vegas

Big River Mine Tailings
St. Francois County,
Missouri

DRAWING NUMBER